## Maintenance

Vehicle No	Make	Model	
4AB0	FORD	ECONOLINE	
G10289	רטאט	ECONOLINE	

PO#	Date	Repair Date	Odometer	<b>Hour Meter</b>	Amount	Status
113903180	09/09/2025 10:00 AM	09/09/2025	189181	0	\$2,295.00	PAID
	09/09/2025 10:54 AM:					
	09/09/2025 10:59 AM:					
	09/09/2025 11:03 AM :					
	09/09/2025 11:03 AM:	PO APPROVE	D FOR \$2,250.0	00 BY MARCU	S SMITH ON	1 09/09/2025
	09/12/2025 11:52 AM:	VehicleExemp	t			
Message	09/09/2025 9:56 AM					
110309202	02/10/2025 7:21 PM	02/10/2025	189081	0	\$356.99	PAID
110003202	02/10/2025 07:21 PM :					וואו
	02/10/2025 07:21 PM:			_		
	02/10/2025 07:24 PM :		-		_	THIS PART/SE
	02/10/2025 07:40 PM :					
	02/10/2025 07:41 PM :					
	02/10/2025 07:44 PM :		•	•		
	02/10/2025 07:44 PM :					
	02/10/2025 07:44 PM :	WAITING FOR	R VENDOR NOT	ES		
	02/10/2025 07:45 PM:	VENDOR 0375	519CC YAR REM	MINDER SENT	ON FEB/10	/2025 19:45:14
	02/10/2025 08:10 PM:	1E001006 - LC	OF (LUBE, OIL, &	& FILTER) - PF	REVENTIVE	MAINT CUST
	02/10/2025 08:10 PM:		•	,		
	02/10/2025 08:10 PM:	1G001001 - D	OT INSPECTION	N - PREVENTI	VE MAINT	THIS PART/SE
	02/10/2025 08:24 PM:	1E001006 - LC	OF (LUBE, OIL, &	& FILTER) - PF	REVENTIVE	MAINT SERY
	02/10/2025 08:25 PM:	PO APPROVE	D FOR \$220.59	BY HOLMAN	ON 02/10/20	)25
	02/10/2025 08:25 PM:	VENDOR EMA	AIL SENT.SUBJE	ECT: REPAIR A	AUTHORIZA	TION
	02/11/2025 12:05 PM:	PO APPROVE	D FOR \$570.58	BY HOLMAN	ON 02/11/20	)25
	02/11/2025 04:09 PM:	DELETED LIN	E - 02019019 - 0	COMPARTMEN	NT DOOR H	ANDLE - PART:
	02/11/2025 04:45 PM:					
	02/11/2025 04:49 PM:					
	02/11/2025 04:52 PM:				•	•
	02/11/2025 04:52 PM:					
	02/11/2025 04:52 PM:					
	02/12/2025 12:11 PM :		D FOR \$349.99	BY HOLMAN	ON 02/12/20	)25
	02/13/2025 12:21 PM :	•				
108802751	11/21/2024 2:04 PM	11/21/2024	188472	0	\$295.72	PAID
	11/21/2024 02:06 PM :				<b></b>	
	11/21/2024 02:08 PM :		D FOR \$289.92	BY HOLMAN	ON 11/21/20	)24
	11/28/2024 08:29 PM :			_	<b>^</b>	
105568328	05/04/2024 3:05 PM	05/04/2024	187482	. 0	\$378.19	PAID
	05/04/2024 03:06 PM :				/	<b>.</b>
	05/04/2024 03:07 PM :					RI: 5/32
	05/04/2024 03:10 PM :					
	05/09/2024 12:59 PM :					
	05/09/2024 12:59 PM :		D FOR \$370.77	RA HOTWAN	ON 05/09/20	)24
10101115	05/09/2024 01:03 PM :	•	40====		0044==	DAID
104314406	02/15/2024 10:21 AM	02/15/2024	187252	0	\$244.75	PAID
	02/15/2024 10:22 AM :					
	02/15/2024 10:25 AM :		D FOR \$239.95	BY HOLMAN	ON 02/15/20	)24
	02/20/2024 10:21 AM:	ıax∟xempt				

Message 01/09/2024 1:03 PM

103697492 \$3,904.98 PAID 01/09/2024 11:29 AM 01/09/2024 187215 0 01/09/2024 11:30 AM: annual commercial inspection - upon inspection vehicle needs 01/09/2024 12:40 PM: loose front sway bar bushingspass's side rear barn door rusted and crack 01/09/2024 12:50 PM: 02021001 - REAR DOOR ASSEMBLY - LABOR - DOES THIS INCLUDE 01/09/2024 12:51 PM: PC REVIEW: RETURNED TO VENDOR FOR MORE NOTES 01/09/2024 12:51 PM: VENDOR EMAIL SENT. SUBJECT: REPAIR AUTHORIZATION 01/09/2024 12:51 PM: WAITING FOR VENDOR NOTES 01/09/2024 01:00 PM: 02021001 - REAR DOOR ASSEMBLY - LABOR - DOOR NEEDS TO BE 01/09/2024 01:03 PM: AUTO RESPONSE: CLIENT AUTHORIZATION PROCESS HAS BEEN ( 01/09/2024 04:53 PM: FA JENNIFER NOBLE CALLED AND ASKED IF DOOR ASSY IS NEEDE 01/10/2024 09:08 AM: AUTO\_RESPONSE: AUTHORIZED BY CLIENT - \$3,828.41, APPROVEF 01/10/2024 09:08 AM: AUTO\_RESPONSE: VENDOR EMAILED 02/01/2024 06:50 PM: TaxExempt **PAID** 102888555 11/14/2023 6:38 PM 11/14/2023 102834 \$221.24 11/14/2023 06:38 PM: OIL CHANGE AND SEASONAL TIRE SWAP 11/14/2023 06:40 PM: AXLE: 1 LF: 14/32 RF: 14/32 AXLE: 2 LI: 14/32 RI: 14/32 11/14/2023 06:44 PM: 17999A61 - SEASONAL TIRE CHANGE - LABOR - ARE THE SUMMER 11/14/2023 06:45 PM: WAITING FOR VENDOR NOTES 11/14/2023 07:06 PM: 17999A61 - SEASONAL TIRE CHANGE - LABOR - CLIENT KEEPS THE 11/14/2023 07:06 PM: PO APPROVED FOR \$216.90 BY HOLMAN ON 11/14/2023 11/14/2023 07:06 PM: TaxExempt 99783207 05/03/2023 1:35 PM 185444 \$138.53 **PAID** 05/03/2023 05/03/2023 01:36 PM: oil changeseasonal tire swap 05/03/2023 01:39 PM: PO APPROVED FOR \$124.98 BY HOLMAN ON 05/03/2023 05/04/2023 11:23 AM: TaxExempt Message 01/12/2023 4:09 PM \$1,900.46 PAID 97997674 01/11/2023 1:50 PM 01/11/2023 185094 0 01/11/2023 01:50 PM: commercial annual inspection - upon inspection - right hand side exhaust 01/11/2023 01:53 PM: 1G001006 - QUARTERLY SAFETY INSPECTION; (NON-REGULATORY 01/11/2023 02:05 PM: 1G001006 - QUARTERLY SAFETY INSPECTION; (NON-REGULATORY 01/11/2023 02:05 PM: AUTO RESPONSE: CLIENT AUTHORIZATION PROCESS HAS BEEN ( 01/11/2023 02:05 PM: PC REVIEW: SENT TO CLIENT FOR AUTHORIZATION 01/11/2023 04:18 PM: AUTO RESPONSE: AUTHORIZED BY CLIENT - \$1,803.63, APPROVEF 01/11/2023 04:18 PM: AUTO\_RESPONSE: VENDOR EMAILED 01/12/2023 03:40 PM: disposal fees 01/12/2023 03:44 PM: 53999A13 - SHOP SUPPLIES - PARTS - OFFER BREAK DOWN ON CF 01/12/2023 03:44 PM: VENDOR EMAIL SENT. SUBJECT: REPAIR AUTHORIZATION 01/12/2023 03:44 PM: WAITING FOR VENDOR NOTES 01/12/2023 03:48 PM: 53999A13 - SHOP SUPPLIES - PARTS - 13% OF TOTAL WORK OR M/ 01/12/2023 03:50 PM: PC REVIEW: SENT TO CLIENT FOR AUTHORIZATION 01/12/2023 03:52 PM: AUTO\_RESPONSE: CLIENT AUTHORIZATION PROCESS HAS BEEN I 01/12/2023 04:00 PM: CLIENT MESSAGE: NO IDEA WHAT THE DISPOSAL CHARGE IS FOR 01/12/2023 04:08 PM: THIS IS SHOP SUPPLIES, 13% OF TOTAL WORK OR MAX 96.83\$ - AL 01/12/2023 04:09 PM: AUTO\_RESPONSE: CLIENT AUTHORIZATION PROCESS HAS BEEN I 01/12/2023 04:14 PM: CLIENT MESSAGE: IF IT IS SHOP SUPPLIES, CODE IT AS SHOP SUP 01/12/2023 04:20 PM: PO APPROVED FOR \$1,900.46 BY AUTO\_AUTHORIZATION OK ON 01 01/12/2023 06:56 PM: TaxExempt 11/29/2022 1:26 PM Message 97403468 11/28/2022 10:07 AM 11/28/2022 184698 **PAID** \$843.79 11/28/2022 10:07 AM: CLIENT HAS BROUGHT VEH IN FOR OIL AND FILTER CHANGE, SWA

11/28/2022 10:17 AM: PO APPROVED FOR \$483.00 BY HOLMAN ON 11/28/2022

```
11/29/2022 10:32 AM: AND REAR BRAKES AT 8MM. STEERING AND SUSPENSION OK. SMA
           11/29/2022 12:17 PM: 43002003 - EXHAUST MANIFOLD GASKET - LABOR - WHAT EXACTLY
           11/29/2022 12:18 PM: VENDOR EMAIL SENTSUBJECT: REPAIR AUTHORIZATION
           11/29/2022 12:18 PM : WAITING FOR VENDOR NOTES
           11/29/2022 12:41 PM: 43002003 - EXHAUST MANIFOLD GASKET - LABOR - POSSIBLE EXTF
           11/29/2022 01:26 PM: HPC REVIEW....SENT TO CLIENT FOR APPROVAL
           11/29/2022 01:26 PM: AUTO RESPONSE: CLIENT AUTHORIZATION PROCESS HAS BEEN (
           11/29/2022 04:14 PM: PO HAS BEEN MODIFIED AND NO REPAIRS ARE PENDING FOR AUT
           11/29/2022 04:24 PM: FA JENNIFER NOBLE CALLED TO CHECK IF ANY OF THE REPAIRS (
           11/30/2022 02:17 PM: PERFORM BATTERY AND CHARGING SYSTEM TEST. BATTERY IS LC
           11/30/2022 02:21 PM: ADDED IN ERROR
           11/30/2022 02:22 PM: 1E001007 - OIL DISPOSAL FEE - PREVENTIVE MAINT. - THIS ITEM IS
           11/30/2022 02:31 PM: 1E001007 - OIL DISPOSAL FEE - PREVENTIVE MAINT. - ADJUSTED S
           11/30/2022 03:54 PM: TaxExempt
95617172
           06/22/2022 2:00 PM
                               06/22/2022
                                              183696
                                                        0
                                                                              PAID
                                                                    $133.69
           07/21/2022 03:53 PM: OIL CHANGE AND SEASONAL TIRE SWAP (PERFORMED IN MAY)
           07/21/2022 03:55 PM: PO APPROVED FOR $133.69 BY HOLMAN ON 07/21/2022
           07/21/2022 03:57 PM: TaxExempt
Message
           01/24/2022 4:16 PM
92745940
           01/17/2022 2:02 PM
                               01/17/2022
                                              183208
                                                                    $1.649.31
                                                                              PAID
           01/17/2022 02:02 PM: COMMERCIAL VEHICLE INSPECTION
           01/17/2022 02:03 PM: ROTATE INCLUDED IN CVIP - N/C AIR FILTER RECOMMENDED BY A
           01/17/2022 02:04 PM: PO APPROVED FOR $337.49 BY ARI ON 01/17/2022
           01/17/2022 06:33 PM: ROTATIONAL NOISE FROM BELT, REQUIERD TENSIONER AND SER
           01/17/2022 06:37 PM: GEAR SELECTOR IS LOOSE, WILL FALL OUT OF GEAR, REQUIRES
           01/17/2022 06:42 PM: APC REVIEW.
           01/17/2022 06:46 PM: AUTO RESPONSE: CLIENT AUTHORIZATION PROCESS HAS BEEN (
           01/18/2022 03:28 PM: AUTO_RESPONSE: AUTHORIZED BY CLIENT - $1,624.31
           01/18/2022 03:28 PM: AUTO_RESPONSE: VENDOR EMAILED
           01/21/2022 03:22 PM: SHOP SUPLPIES
           01/21/2022 03:23 PM: AUTO_RESPONSE: CLIENT AUTHORIZATION PROCESS HAS BEEN I
           01/21/2022 04:08 PM: AUTO_RESPONSE: AUTHORIZED BY CLIENT - $1,649.31, APPROVEF
           01/21/2022 04:08 PM: AUTO RESPONSE: VENDOR EMAILED
           01/24/2022 03:58 PM: WOULD NOT START WHEN CUSTOMER CAME TO PICK UP. BATTER
           01/24/2022 04:16 PM: NOTE TO FA: THE CURRENTLY INSTALLED BATTERY STILL HAVE 8
           01/24/2022 04:16 PM: AUTO_RESPONSE: CLIENT AUTHORIZATION PROCESS HAS BEEN F
           01/24/2022 05:32 PM: PO HAS BEEN MODIFIED AND NO REPAIRS ARE PENDING FOR AUT
           01/24/2022 05:33 PM: FA CALLED IN, BATTERY SHOULD BE COVERD AT STONEY TRAIL M
           01/25/2022 12:07 PM: TaxExempt
92164246
                                                        0
           12/02/2021 11:55 AM
                              12/02/2021
                                              182602
                                                                    $801.62
           12/02/2021 11:56 AM: OIL CHNAGE, INSPECTION, TIRE ROTATION. INSTALL SUPLPIED TIF
           12/02/2021 12:17 PM: APC REVIEWED, NEED SUMMER TIRE TREAD READINGS
           12/02/2021 12:18 PM: NEEDS SUMMER TIRE TREAD READINGS, IS THE DRIVER TAKING E
           12/02/2021 12:18 PM: 17999A61 - SEASONAL TIRE CHANGE - LABOR - NEEDS SUMMER TI
           12/02/2021 12:18 PM: WAITING FOR VENDOR NOTES
           12/02/2021 06:36 PM: 17999A61 - SEASONAL TIRE CHANGE - LABOR - DRIVER SUPPLIED.
           12/02/2021 06:42 PM: PC ... VENDOR PROVIDED INFOR ... STILL MISSING INFOR ... NEW (
           12/02/2021 06:42 PM: 17999A61 - SEASONAL TIRE CHANGE - LABOR - PLEASE PROVIDE /
           12/02/2021 06:43 PM: VENDOR EMAIL SENT. SUBJECT: REPAIR AUTHORIZATION
           12/02/2021 06:43 PM: WAITING FOR VENDOR NOTES
           12/02/2021 06:43 PM: 17999A61 - SEASONAL TIRE CHANGE - LABOR - PLEASE PROVIDE /
           12/02/2021 06:47 PM: WEB REQUEST BEING PROCESSED BY ANOTHER USER
           12/02/2021 06:47 PM: 17999A61 - SEASONAL TIRE CHANGE - LABOR - NEED SUMMER TRI
           12/03/2021 10:07 AM: 17999A61 - SEASONAL TIRE CHANGE - LABOR - INCLUDED IN INSPE
```

```
12/03/2021 10:18 AM: 17999A61 - SEASONAL TIRE CHANGE - LABOR - CALLED SHOP NO F
           12/03/2021 10:18 AM: VENDOR EMAIL SENT. SUBJECT: REPAIR AUTHORIZATION
           12/03/2021 10:18 AM: WAITING FOR VENDOR NOTES
           12/03/2021 01:01 PM: 17999A61 - SEASONAL TIRE CHANGE - LABOR - SUMMER TIRES AR
           12/03/2021 01:23 PM: PO APPROVED FOR $345.01 BY ARI ON 12/03/2021
           12/03/2021 01:23 PM: VENDOR EMAIL SENT. SUBJECT: REPAIR AUTHORIZATION
           12/03/2021 01:36 PM: REQUIRES AUX BATTERY LOCATED IN FENDER WALL RATED FOR
           12/03/2021 02:12 PM: DELETED LINE - 40001004 - ENGINE DIAGNOSIS - PREVENTIVE MAII
           12/03/2021 02:12 PM : REVIEW
           12/03/2021 02:12 PM: VENDOR EMAIL SENT. SUBJECT: REPAIR AUTHORIZATION
           12/03/2021 02:12 PM: WAITING FOR VENDOR NOTES
           12/03/2021 04:33 PM: DELETED LINE - 40001004 - ENGINE DIAGNOSIS - PREVENTIVE MAII
           12/07/2021 03:14 PM: REMOVING DIAG FOR ROTATIONAL ENGINE NOISE. -
           12/07/2021 03:16 PM: NOT REQUIRED
           12/07/2021 03:16 PM: PO APPROVED FOR $801.62 BY ARI ON 12/07/2021
           01/17/2022 01:54 PM: TaxExempt
92079712
           11/26/2021 1:00 PM
                               11/26/2021
                                               182347
                                                        0
                                                                    $336.68
                                                                               PAID
           11/26/2021 01:57 PM: CUSTOMER BROUGHT IN LOOSE TIREWITH NAIL IN SIDE WALL CA
           11/26/2021 02:12 PM: 245/75/16 LT, INSTALLING BFG COMMERCIAL TA AS
           11/26/2021 02:14 PM: PO APPROVED FOR $340.68 BY ARI ON 11/26/2021
           01/13/2022 04:34 PM: FA JENNIFER NOBLE CALLED TO HAVE PO CLOSED OUT. SPOKE T
           01/13/2022 04:40 PM: PO APPROVED FOR $336.68 BY ARI ON 01/13/2022
           01/13/2022 04:40 PM: WAITING ON VENDOR TO CALL BACK AND CLOSE OUT PO ASPER I
           01/13/2022 04:41 PM: TaxExempt
89986716
           07/07/2021 3:37 PM
                               07/07/2021
                                               177305
                                                         Λ
                                                                    $98.28
                                                                               PAID
           07/07/2021 03:42 PM: CUSTOMER REQUESTED OIL CHANGE
           07/07/2021 03:46 PM: PO APPROVED FOR $98.28 BY ARI ON 07/07/2021
           07/07/2021 04:07 PM: TaxExempt
89013101
           05/04/2021 3:00 PM
                               05/04/2021
                                               174426
                                                         0
                                                                    $90.00
                                                                               PAID
           05/04/2021 03:14 PM : CANE OPEN PO
           05/04/2021 03:14 PM: INSTALL GPS
           05/04/2021 03:15 PM: PO APPROVED FOR $90.00 BY ARI ON 05/04/2021
           05/05/2021 09:52 AM: TaxExempt
           01/29/2021 12:44 PM
Message
87520355
           01/20/2021 6:29 PM
                               01/20/2021
                                               171660
                                                         0
                                                                    $7.801.74 PAID
           01/20/2021 06:29 PM: COMMERCIAL VHICLE INSPECTION. - PASSENGER REAR LEAF SPR
           01/20/2021 06:30 PM: OIL CHANGE. TIRE REPAIR - NOTE TIRES ARE 1/32 ABOVE PASS, R
           01/20/2021 06:39 PM: TIRE SIZE:245/75 R16, MANUFACTURER:MICHELIN, MODEL:BFG CO
           01/20/2021 07:13 PM: APC REVIEWED: ADJUSTED LABOR ON RADIATOR FROM 2.5HR TO
           01/20/2021 07:16 PM: 42002001 - RADIATOR - LABOR - ADJUSTED PER LABOR GUIDE
           01/20/2021 07:20 PM: 02024001 - WINDSHIELD - PARTS - PLEASE PROVIDE NOTES - NEEL
           01/20/2021 07:21 PM: WAITING FOR VENDOR NOTES
           01/20/2021 07:21 PM: 42002001 - RADIATOR - PARTS - .
           01/21/2021 09:46 AM: WINDSHIELD IS CRACKED AND THAT IS A SUBLET CRACKED FROM
           01/21/2021 09:47 AM: VDR CALLING TO UPDATE PO......VDR DECLINED NEGO SINE UPFIT
           01/21/2021 09:47 AM: PO IS PENDING FA INFORMATION
           01/21/2021 09:47 AM: AUTO_RESPONSE: CLIENT AUTHORIZATION PROCESS HAS BEEN (
           01/22/2021 01:41 PM: MD MICKEY CLLD ON PRICING ON TIRES.. SHOW NO NOTES ON T
           01/22/2021 03:41 PM: FA CB STATES HE WILL APPROVE IF VENDOR MATCH NA PRICING (
           01/22/2021 03:47 PM: PO APPROVED FOR $6,185.71 BY MARCUS SMITH ON 01/22/2021
           01/26/2021 12:34 PM: TIRE PRESSURE SENSORS WILL NOT TRAIN, NO SENSOR WILL TR
           01/26/2021 01:07 PM: REVIEWED AND SENT FOR REAPPROVAL OF ADDITIONAL
           01/26/2021 01:07 PM: AUTO_RESPONSE: CLIENT AUTHORIZATION PROCESS HAS BEEN I
           01/26/2021 04:05 PM: FA MARCUS SMITH CLLD TO REVIEW, AUTH ADDED DIAG
```

```
01/26/2021 04:12 PM: PO HAS BEEN MODIFIED AND NO REPAIRS ARE PENDING FOR AUT
           01/26/2021 04:12 PM: Vendor Notification: Vendor emailed: for $6334.71
           01/27/2021 04:43 PM: diagnosed tpms issue to be the smart junction box, requires the SJB, and
           01/27/2021 04:47 PM: REVIEW APC AND SEND EST TO FA FOR REVIEW--
           01/27/2021 04:47 PM: AUTO_RESPONSE: CLIENT AUTHORIZATION PROCESS HAS BEEN I
           01/28/2021 11:10 AM: AUTO_RESPONSE: AUTHORIZED BY CLIENT - $7,100.39
           01/28/2021 11:10 AM: AUTO RESPONSE: VENDOR EMAILED
           01/28/2021 01:43 PM: ISTALLED SJB, AND SENSORS STILL WILL NOT TRAIN. VEHICLE IS
           01/28/2021 01:58 PM: PC REVIEW: ADDITION REQUIRES CLIENT APPROVAL
           01/28/2021 01:58 PM: AUTO_RESPONSE: CLIENT AUTHORIZATION PROCESS HAS BEEN I
           01/28/2021 04:01 PM: FA MARCUS SMITH CLLD TO REVIEW, SOUNDS LIKE MD MISDIAGN
           01/29/2021 12:42 PM: SHOP CALLED TO CHECK STATUS = RE SENT FOR APPROVAL =
           01/29/2021 12:43 PM: FRONT LH TIE ROD SLEEVE WAS SEIZED, NOT ABLE TO FREE IT (
           01/29/2021 12:44 PM: PO IS PENDING FA INFORMATION
           01/29/2021 12:44 PM: AUTO_RESPONSE: CLIENT AUTHORIZATION PROCESS HAS BEEN I
           01/29/2021 01:20 PM: FA MARCUS SMITH CALLED TO REVIEW-- FA WANTS TO VERIFY IF
           01/29/2021 01:40 PM: MD MICKEY C/B STATED OLD JUNCTION BOX WOULD NOT PROGI
           02/01/2021 10:24 AM: AUTO_RESPONSE: AUTHORIZED BY CLIENT - $7,801.74,
           02/01/2021 10:24 AM: AUTO RESPONSE: VENDOR EMAILED
           02/02/2021 03:41 PM: TaxExempt
86242850
           10/23/2020 3:08 PM
                                10/23/2020
                                               166733
                                                                     $442.97
                                                                               PAID
           10/23/2020 03:11 PM:
           10/23/2020 03:11 PM: CUSTOMER STATES BATTERY WAS DIAGNOS AND REPLACE BATT
           10/23/2020 03:15 PM: CUSTOMER STATES-BATTERY WAS DEAD, DIAGNOS AND REPLACI
           10/23/2020 03:16 PM: OIL CHANGE SERVICE
           10/23/2020 03:20 PM: OIL CHANGE SERVICE
           10/23/2020 03:20 PM: PO APPROVED FOR $350.03 BY ARI ON 10/23/2020
           10/23/2020 03:25 PM: TaxExempt
82994421
           03/20/2020 12:00 AM 03/20/2020
                                               460469
                                                                     $798.00
                                                                               PAID
           03/26/2020 10:31 AM: INV 48154 RPAIRS COMPLETED 03/20/2020 PM OK ATF ALL REPAIF
           03/26/2020 10:34 AM: IN FOR A VENTILATION PROBLEM AT THE REAR OF UNIT FANS INO
           03/26/2020 10:36 AM: PO APPROVED FOR $798.00 BY ARI ON 03/26/2020
82769054
           03/10/2020 3:47 PM
                               03/10/2020
                                               160454
                                                                     $939.00
                                                                               PAID
           03/10/2020 03:50 PM: UNIT IN FOR 4 NEW TIRES // TIRES OFF 245/75R16 MICHELIN LTX W
           03/10/2020 03:53 PM: TIRE SIZE:245/75 R16, MANUFACTURER:NOKIAN, MODEL:E10 NOKI/
           03/10/2020 03:54 PM: DELETED LINE - 15999A01 - FRONT END ALIGNMENT - PREVENTIVE
           03/10/2020 04:06 PM: DELETED LINE - 17001001 - TIRE, RADIAL LUG TREAD - PARTS - ON
           03/10/2020 04:06 PM: REVIEWED APC EVENT.....REQUEST MORE NOTES FROM VENDOR
           03/10/2020 04:06 PM: VENDOR EMAIL SENT. SUBJECT: REPAIR AUTHORIZATION
           03/10/2020 04:06 PM: WAITING FOR VENDOR NOTES
           03/10/2020 04:22 PM: S/A LISA CALLED TO REVIEW ... WENT TO TECH TOOLS UNDER TH
           03/10/2020 04:41 PM: VENDOR LISA LDFC CALLED IN TO CHANGE TO MICHELIN NATIONAL
           03/10/2020 04:41 PM: LT245/75R16 MICHELIN LX / AT2 PN: 52691
           03/10/2020 04:46 PM: PO APPROVED FOR $1,305.00 BY CLIENT PARMS ON 03/10/2020
           03/27/2020 12:23 PM: 07600334
           03/27/2020 12:23 PM: MT20079 - PAID INV# 07600334
82760155
           03/10/2020 10:46 AM 03/10/2020
                                               160432
                                                         0
                                                                     $880.28
                                                                               PAID
           03/10/2020 10:46 AM: SEMI ANNUAL D.O.T INSPECTIONWILL REQUIRE CAGE REPAIR TO F
           03/10/2020 10:46 AM: SERVICE DUEAIR FILTER DIRTY
           03/10/2020 10:46 AM: TIRES HAVE SIDEWALL CRACKINGCORRECTIONS SHOULD BE SUP
           03/10/2020 10:47 AM: WINDSHIELD CRACKED
           03/10/2020 11:07 AM : PO APPROVED FOR $1,024.11 BY ARI ON 03/10/2020
           03/20/2020 10:02 AM: HAD TO RE DO INSPECTION AS IT LAPSED
           03/20/2020 10:10 AM: 1G001F01 - FAILED DOT INSPECTION - PREVENTIVE MAINT. - THE A
           03/20/2020 10:10 AM: PO pending acceptance from vendor for $847.39
```

03/20/2020 10:10 AM: VENDOR EMAIL SENT. SUBJECT: REPAIR AUTHORIZATION

03/20/2020 10:10 AM: Initial negotiation rejected by supplier. Please review parts pricing and lat

03/20/2020 10:13 AM : PC REVIEW

03/20/2020 10:13 AM : CHANGED CODE ON LINE 2.2

03/20/2020 10:31 AM: TaxExempt

Message 10/29/2019 10:44 AM

## 78497509 06/06/2019 11:04 AM 06/06/2019 146367 \$538.41 PAID

06/06/2019 11:05 AM: HEATER FAN IS NOT WORKINGFOUND RESISTOR BURNT OUT AND

06/06/2019 11:09 AM: PO pending acceptance from vendor for \$483.63

06/06/2019 11:09 AM: VENDOR EMAIL SENT. SUBJECT: REPAIR AUTHORIZATION

06/06/2019 11:10 AM: Initial negotiation rejected by supplier. Please review parts pricing and lat

06/06/2019 11:35 AM: AUTH FOR \$ 538.41 BT

06/06/2019 11:35 AM: PO APPROVED FOR \$538.41 BY ARI ON 06/06/2019

06/06/2019 11:35 AM: VENDOR EMAIL SENT. SUBJECT: REPAIR AUTHORIZATION

06/11/2019 10:20 AM: TaxExempt

Message 04/18/2019 12:35 PM

## 77579247 04/12/2019 4:00 PM 04/12/2019 144538 \$7,107.35 PAID

04/12/2019 04:24 PM: DOT INSPECTION, INSPECTION, PROVIDE ESTIMATE FOR REPAIRS 04/12/2019 04:39 PM: BRAKE PAD MEASUREMENTS: AXLE: 2 LEFT: 3 MM RIGHT: 3 MW 04/12/2019 04:39 PM: BRAKE ROTOR MEASUREMENTS: AXLE: 2 LEFT: 35.68 MM RIGHT: 3 MW 04/12/2019 04:52 PM: 43002001 - EXHAUST MANIFOLD - PREVENTIVE MAINT. - NEED PAF 04/12/2019 04:52 PM: 16004007 - FRONT SWAY BAR BUSHING - PREVENTIVE MAINT. - NE 04/12/2019 04:53 PM: 40001004 - ENGINE DIAGNOSIS - PREVENTIVE MAINT. - ESTIMATE F 04/12/2019 04:53 PM: 22003014 - DIFFERENTIAL CASE COVER - DRIVEN REAR AXLE - PRE 04/12/2019 04:53 PM: 27031004 - CASE EXTENSION HOUSING SEAL - AUTO TRANS - PREV 04/12/2019 04:55 PM: MAITING FOR VENDOR NOTES

04/15/2019 04:57 PM: 16004007 - FRONT SWAY BAR BUSHING - PREVENTIVE MAINT. - 1.2 04/15/2019 04:57 PM: 1G001001 - DOT INSPECTION - PREVENTIVE MAINT. - 29.95 0.3 HRS 04/15/2019 04:57 PM: 22003014 - DIFFERENTIAL CASE COVER - DRIVEN REAR AXLE - PRE 04/15/2019 04:57 PM: 27031004 - CASE EXTENSION HOUSING SEAL - AUTO TRANS - PRE 04/15/2019 04:57 PM: 40001004 - ENGINE DIAGNOSIS - PREVENTIVE MAINT. - WILL GET IT 04/15/2019 05:02 PM: 43002001 - EXHAUST MANIFOLD - PREVENTIVE MAINT. - SEE NOTE

04/15/2019 05:03 PM: 43002001 - EXHAUST MANIFOLD - LABOR - .

04/15/2019 05:03 PM: 43002001 - EXHAUST MANIFOLD - PREVENTIVE MAINT. - .

04/15/2019 05:04 PM: AUTO\_RESPONSE: CLIENT AUTHORIZATION PROCESS HAS BEEN \$ 04/17/2019 11:29 AM: F/A JORDAN REILING (P) CALLED TO REVIEW, AUTH REPAIRS PEND 04/18/2019 12:22 PM: NEEDS REAR MAIN SEAL...

04/18/2019 12:28 PM : S/A DAGG CALLING WITH UPDATE - ADJUST LINE ITEMS AS REQUIF 04/18/2019 12:35 PM : AUTO\_RESPONSE: CLIENT AUTHORIZATION PROCESS HAS BEEN F

04/18/2019 01:09 PM: AUTO\_RESPONSE: AUTHORIZED BY CLIENT - \$5,331.09

04/18/2019 01:12 PM: VENDOR RECIEVED APPROVAL ON PARTNER CONNECT

04/18/2019 01:13 PM: F/A JORDAN CALLED TO ASK IF ARI ASKED VDR TO BUILT ESTIMAT 04/18/2019 01:26 PM: CALLED OUT TO SHOP - NO ANSWER, LEFT MSG FOR S/A DAGG T( 05/14/2019 02:02 PM: Story: 144538 6113((13.7HRS TOTAL, 3.5HRS MANIFOLD, 5.7HRSENG 06/01/2019 02:45 PM: (((15.2HRS TOTAL, 1.0HRS LEAK DIAG, 13.7HRSREAR MAIN SEAL, 0. 06/01/2019 02:59 PM: APC REVIEWED,, REQUEST VDR TO SPEAK TO AN ARI TECH VDR 06/01/2019 02:59 PM: DELETED LINE - 45002012 - REAR MAIN SEAL - PREVENTIVE MAINT 06/01/2019 02:59 PM: DELETED LINE - 43002026 - EXHAUST MANIFOLD STUD - PREVENTI 06/01/2019 03:01 PM: WAITING FOR VENDOR NOTES

07/10/2019 01:38 PM: MD JENNIFER CLD REQ STATUS - ADVISED UNDER REVIEW

07/10/2019 01:45 PM: SA STATES WCB WITH COMPLETE BREAKDOWN OF PARTS / LABO 10/22/2019 01:41 PM: SHELBY CALLED TO REPORT THERE WERE 7 BROKEN STUDS. VEN

```
10/22/2019 01:58 PM: S/A SHELBY CALLED TO ADD 10.2 EXTRA HOURS OF LABOR TO RE
           10/29/2019 10:33 AM: MD SHELBY CALLED TO GO OVER TOTALS...TOTALS MATCHING. SI
           10/29/2019 10:39 AM: MD STS REAR DIFF COVER GASKET IS LEAKING, PERFORMED SER
           10/29/2019 10:42 AM: DRV REQ 2 NEW KEY FOBS...DOES NOT KNOW WHY REQUESTED..
           10/29/2019 10:44 AM: AUTO_RESPONSE: CLIENT AUTHORIZATION PROCESS HAS BEEN I
           10/29/2019 12:43 PM: F/A MARCUS REILING CALLED TO ENQUIRE ABOUT ADDITIONAL LA
           10/30/2019 12:20 PM: AUTO RESPONSE: AUTHORIZED BY CLIENT - $7,107.35
           10/31/2019 07:03 AM: VENDOR RECIEVED APPROVAL ON PARTNER CONNECT
           11/01/2019 02:35 PM: TaxExempt
77436185
           04/03/2019 3:39 PM
                                04/03/2019
                                               144513
                                                                     $469.40
                                                                                PAID
           04/03/2019 03:41 PM: Diag for AC is not working
           04/03/2019 03:41 PM: CVIP inspection due, oil change due.
           04/03/2019 03:48 PM: 1G001001 - DOT INSPECTION - PREVENTIVE MAINT. - NOT DUE UNT
           04/03/2019 03:48 PM: DENIED INSP FOR FIELD ADJ OF 279.95
           04/03/2019 03:48 PM: PO APPROVED FOR $189.45 BY ARI ON 04/03/2019
           04/03/2019 03:48 PM: VENDOR EMAIL SENT SUBJECT: REPAIR AUTHORIZATION
           04/03/2019 04:00 PM: VDR IS CB IN FOR SEMI ANNUAL DOT UNIT IS A BUS.
           04/03/2019 04:00 PM : PO APPROVED FOR $469.40 BY ARI ON 04/03/2019
           04/03/2019 04:00 PM: VDR CB FOR STATUS NEW TOTAL $ 469.40 BTX
           04/03/2019 04:01 PM: TaxExempt
Message
           04/01/2019 1:52 PM
           04/01/2019 1:00 PM
77390331
                                04/01/2019
                                               144510
                                                                     $0.00
                                                                                DECLINED
           04/01/2019 01:27 PM: WO# 383277 -- PM DUE SOON -- NEG LABOR SAVINGS OF $527.00 E
           04/01/2019 01:27 PM: IN FOR LOF -- DRV REQUESTED -- TUNE UP
           04/01/2019 01:27 PM: DOT INSPECLTION
           04/01/2019 01:28 PM : D/C A/C IN//OPP -- NO FAULT FOUND
           04/01/2019 01:29 PM: REAR MAIN SEAL ACTIVE LEAK -- REPLACE -- OIL PAN GASKET LEA
           04/01/2019 01:38 PM: REAR BRAKES 2MM ROTORS NOT MACHINABLE RUSTED AND PITT
           04/01/2019 01:41 PM: CLIENT STATED KEY FOBS WENT THROUGH A WASHING MACHINE
           04/01/2019 01:42 PM: RADIATOR LEAKING FROM BACK SIDE, REPLACE
           04/01/2019 01:44 PM: TRANSMISSION EXT HOUS SEAL LEAKING, REPLACE -- REQUESTE
           04/01/2019 01:50 PM: LVEFT FRONT SHOCK LEAKING[ -- REPLACE
           04/01/2019 01:52 PM: AUTO RESPONSE: CLIENT AUTHORIZATION PROCESS HAS BEEN (
           04/03/2019 10:49 AM: F/A MARCUS SMITH CALLED TO REVIEW.
                                                                       DECLINED ALL REPAIF
           04/03/2019 10:52 AM : PO HAS BEEN MODIFIED AND NO REPAIRS ARE PENDING FOR AUT
           04/03/2019 03:38 PM: PO has been voided by vendor (026229CC).
75393711
           11/30/2018 9:47 AM
                                11/30/2018
                                               138305
                                                                     $505.57
                                                                                PAID
           11/30/2018 09:47 AM : OIL CHANGE DUE
           11/30/2018 09:47 AM: OIL DIPSTICK TUBE BROKENLOCATED BEHIND MANIFOLD
           11/30/2018 09:50 AM: PO pending acceptance from vendor for $246.75
           11/30/2018 09:50 AM: VENDOR EMAIL SENT. SUBJECT: REPAIR AUTHORIZATION
           11/30/2018 09:51 AM: Initial negotiation rejected by supplier. Please review parts pricing and lat
           11/30/2018 09:58 AM: APC REVIEWED. APPROVED
           11/30/2018 09:58 AM : PO APPROVED FOR $505.57 BY ARI ON 11/30/2018
           11/30/2018 09:58 AM: VENDOR EMAIL SENT. SUBJECT: REPAIR AUTHORIZATION
           11/30/2018 10:18 AM : TaxExempt
74411393
           09/27/2018 12:56 PM 09/27/2018
                                               134646
                                                                     $660.38
                                                                                PAID
           09/27/2018 12:57 PM: SEMI ANNUAL D.O.T
           09/27/2018 12:57 PM: CUT AND PROGRAM SECOND KEY
           09/27/2018 12:57 PM: REAR CAGE FAN NOT WORKING
           09/27/2018 01:08 PM : PO APPROVED FOR $660.38 BY ARI ON 09/27/2018
           09/27/2018 01:08 PM: VENDOR EMAIL SENT. SUBJECT: REPAIR AUTHORIZATION
           09/27/2018 01:39 PM: TaxExempt
72831255
           06/19/2018 4:24 PM
                                06/19/2018
                                                130149
                                                                     $828.11
                                                                                PAID
```

06/19/2018 04:25 PM: BRAKE PULSATION 06/19/2018 04:26 PM : BRAKE PAD MEASUREMENTS: AXLE: 1 LEFT: 2 MM RIGHT: 2 MM 06/19/2018 04:26 PM: BRAKE ROTOR MEASUREMENTS: AXLE: 1 LEFT: 2 MM RIGHT: 2 06/19/2018 04:27 PM : OIL CHANGE DUE 06/19/2018 04:27 PM: PO APPROVED FOR \$828.11 BY ARI ON 06/19/2018 06/22/2018 11:35 AM: TaxExempt 74050767 04/30/2018 12:00 AM 04/30/2018 125453 \$220.00 PAID 09/04/2018 01:08 PM: WO# 41134...ISSUED PO AND PAID \$220.00 09/04/2018 01:08 PM: 2-WAY RADIO SWAP - SUPPLIED 09/04/2018 01:09 PM: PO APPROVED FOR \$220.00 BY ARI ON 09/04/2018 08/29/2017 68245326 08/29/2017 3:00 AM 115297 \$611.10 PAID 08/31/2017 03:19 PM: WO#167367.....ATF...PAID .... 08/31/2017 03:19 PM: DOT.....#CV5873817.... 08/31/2017 03:19 PM: LOF.... 08/31/2017 03:19 PM: PASENGER SIDE HEATER VENT BROKEN ...REPLACE.... 08/31/2017 03:21 PM: PO APPROVED FOR \$611.10 BY ARI ON 08/31/2017 64717938 02/01/2017 3:00 PM 02/01/2017 104837 \$1.049.85 PAID 02/01/2017 03:35 PM: WO# 162075...ISSUED PO TO SHAWNA FOR \$ 1049.85 BT 02/01/2017 03:36 PM: DOT INSPECTION... 02/01/2017 03:36 PM: LOF... 02/01/2017 03:37 PM: VDR STATES THAT REAR DOOR LOCK CYL ON SWING DOOR AND F 02/01/2017 03:38 PM: PO APPROVED FOR \$1,049.85 BY ARI ON 02/01/2017 05/05/2017 12:14 PM: CHECKING OPEN PO'S 60468793 07/07/2016 11:00 AM 07/07/2016 \$779.34 PAID 95379 07/07/2016 11:16 AM: WO 157170.......PM IS DUE, DOT IS DUE EVERY 6 MOS......ISSU 07/07/2016 11:16 AM: IN FOR LOF 07/07/2016 11:16 AM: DOT 07/07/2016 11:17 AM: FOUND LEFT SIDE UPPER AND LOWER BALL JOINTS LOOSE, REQ | 07/07/2016 11:20 AM : PO APPROVED FOR \$779.34 BY ARI ON 07/07/2016 07/12/2016 09:37 AM : CALLED IN BY SHAWN 56396816 01/11/2016 12:00 AM 01/11/2016 \$1,235.60 **PAID** 87835 01/12/2016 02:45 PM: WO# 153132 .. ISSUED PO# FOR \$1235.66BT 01/12/2016 02:46 PM : CVIP - DECAL# 01/12/2016 02:46 PM: LOF 01/12/2016 02:49 PM: BLOCK HEATER CORD DAMAGED REPLACE 01/12/2016 02:49 PM: FOUND:: LH MIRROR MOTOR NOT WORKING, DOES NOT STAY IN F 01/12/2016 02:50 PM: FOUND:: W/S CRACKED REPLACE... DW0 01/12/2016 02:56 PM: PO APPROVED FOR \$1,235.66 BY ARI ON 01/12/2016 03/08/2016 11:44 AM : CALLED IN BY SHAWN TO CLOSE 54078956 07/20/2015 4:00 PM 07/20/2015 **PAID** \$78.33 07/20/2015 04:18 PM: MD KATIE CLD REF LOF - ROT 07/20/2015 04:19 PM: PO APPROVED FOR \$78.33 BY ARI ON 07/20/2015 07/20/2015 04:20 PM: CURRENT REPAIR - INV#273421 - ISSUED AND CLOSED FOR 78.33 I 51670470 01/26/2015 5:00 PM 01/26/2015 1 \$473.20 01/26/2015 05:56 PM: WO# 620246845 - PM CHECKED - OK - REQUEST VIA EMAIL FROM S 01/26/2015 05:57 PM: SUPPLY 2 TIRES LT245/75R16 10PLY - LTX WINTER - PC# 14719IN 01/26/2015 06:00 PM: PO APPROVED FOR \$528.40 BY ARI ON 01/26/2015 51640884 01/23/2015 4:00 PM 01/23/2015 72161 \$822.12 **PAID** 01/23/2015 04:41 PM: WO 267060....ISSUED PO AND PAID \$627.82AT 01/23/2015 04:42 PM: CHECK ENGINE LIGHT ON, DIAGNOSE...EVAP PRESSURE VALVE F/ 01/23/2015 04:43 PM: LOF...TIRE ROTATION INSPECTION... 01/23/2015 04:44 PM : PO APPROVED FOR \$627.82 BY ARI ON 01/23/2015 01/26/2015 08:51 AM: BATTERY FAILED LOAD TEST DUREST AN INSP.. NO COMPL FROM 01/26/2015 08:52 AM: VDR CB, UPDATED .. NEW S/TOTAL \$ 831.37 BFT 01/26/2015 11:44 AM: IV CLLD TO UPDATE AND CLOSE

Message 11/29/2014 2:32 PM

50162702	11/29/2014 2:00 PM	11/29/2014	70068	\$5,307.49	PAID
	11/29/2014 02:25 PM:	DOT			
	11/29/2014 02:25 PM:	MD FOUND STE	ERING GEAR BO	OX LEAKING,,,REC REF	PLACE
				SHOCKS LEAKING,,,RE	
	11/29/2014 02:26 PM:	MD FOUND FRO	ONT BRAKE ROT	ORS, RUSTED, PITTED	AND WARPE
	11/29/2014 02:27 PM:	MD FOUND TRA	ANS OUTPUT SE	AL LEAKING,,,REC REF	PLACE
	11/29/2014 02:32 PM:	AUTO_RESPON	ISE: CLIENT AUT	THORIZATION PROCES	S HAS BEEN S
	11/29/2014 02:32 PM:	WO#294561			
	12/01/2014 12:05 PM:	AUTO_RESPON	ISE: AUTHORIZE	D BY CLIENT - \$5,395.8	37, APPROVEF
	12/01/2014 12:55 PM:	CALLOUT: SPO	KE TO S/A MICH	AEL, AUTH @\$ 5,395.8	7 BFT.PO#RI
	12/09/2014 01:30 PM:	ADVISED MICH	EAL NOT PAID	WORK NOT COMPLE	TED
	02/27/2015 12:55 PM:	ADVISED VDR	THAT THIS PO ST	TILL OPENVDR WEN	THOURGH N
	02/27/2015 12:55 PM:	INFORMED VDF	R THAT THE REP	AIR SHOULD BE WATT	ANTY
45970371	06/04/2014 12:00 PM	06/04/2014	61680	\$336.66	PAID
	06/04/2014 12:17 PM :	WO#139438PI	M WAS DUE,IS	SUED PO FOR \$336.66	BT, VDR TO C
	06/04/2014 12:18 PM:	IN FOR COMME	RCIAL VEHICLE	INSPECTIONCERT	# CV5188903
	06/04/2014 12:18 PM :	RR TIRE LOSIN	G AIR, VALVE ST	TEM LEAKING, REPLAC	CE
	06/04/2014 12:22 PM :				
	06/05/2014 11:39 AM :				
45470791	04/22/2014 6:00 PM	04/22/2014	60063	\$207.45	PAID
	04/22/2014 06:14 PM :	WO#30008083.	PM COMING D	UE, VDR WILL NOTIFY	DRIVER ISS
	04/22/2014 06:14 PM:	IN FOR WINDSI	HIELD CRACKED	, REPALCE DW#1504G	BY PRICE C
	04/22/2014 06:16 PM:	PO APPROVED	FOR \$207.45 BY	ARI ON 04/22/2014	
44627261	12/04/2013 12:00 AM	12/04/2013	54471	\$361.68	PAID
	02/19/2014 10:29 AM:	W/O NO # 25254	46. ATF CALL CC	MPLETED. ( NOT NEG	OI). NO DOT
	02/19/2014 10:31 AM:	LOF. VEH IS FO	R ANU DOT INSI	P. PASSED.	•
	02/19/2014 10:33 AM:	REPAIRED RIGI	HT FRONT TIRE	FLAT ( TPMS LIGHT ON	<b>l</b> ).
	02/19/2014 10:35 AM:	PO APPROVED	FOR \$361.68 BY	' ARI ON 02/19/2014	
44674070	08/15/2013 12:00 AM	08/15/2013	49936	\$294.53	PAID
44674069	07/12/2013 12:00 AM	07/12/2013	49936	\$1,613.73	PAID
44674068	12/07/2012 12:00 AM	12/07/2012	40823	\$409.75	PAID
44674067	11/13/2012 12:00 AM	11/13/2012	40823	\$979.23	PAID
44674066	04/19/2012 12:00 AM	04/19/2012	31881	\$559.80	PAID
44674065	02/10/2012 12:00 AM	02/10/2012	28961	\$213.70	PAID
44674064	10/07/2011 12:00 AM	10/07/2011	24191	\$574.63	PAID
44674063	06/17/2011 12:00 AM	06/17/2011	17911	\$271.06	PAID
44674062	05/11/2011 12:00 AM	05/11/2011	15920	\$169.18	PAID
44674061	03/02/2011 12:00 AM	03/02/2011	11796	\$309.11	PAID
44674060	02/08/2011 12:00 AM	02/08/2011	11796	\$42.84	PAID
44674059	09/24/2010 12:00 AM	09/24/2010	2333	\$249.95	PAID
				Ψ= .0.00	· ··=

<b>Process Date</b>	Invoice #	Vendor
09/12/2025	40209	KEE-LOK SECURITY SUPPLIES (I)

3 LIGHTS AND WIRING, EQUIPMENT WILL BE RETURNED TO CLIENT IR KEE'LOCK AND AUTH \$2250, CLD VENDOR TO GET ESTIMATE AND PROVIDE A

02/13/2025 861120 UNIVERSAL FORD LINCOLN (I)

ERVICE IS NOT PERMITTED FOR THIS VEHICLE.

LUESTED FOE EARLY LOF. LAST LOF WAS AT188417. DUE AT 200417 / 5/21/20 NOTES. WHAT TYPE OF INSPECTION./ DOT. / STATE INSPECTION.. OR CLIEF

OMER REQUESTED - WILL ADVISE

MERCIAL VEHICLE INSPECTION - DUE EVERY YEAR - LAST ONE DONE FEB 2/24

ERVICE IS NOT PERMITTED FOR THIS VEHICLE.

VICE ITEM IS NOT DUE PER HOLMAN OR CLIENT MAINTENANCE SCHEDULE

S - 3 C'S MISSING 1 OR MORE. DRIVER COMPLAINT - CAUSE, WHY PART NEEDS S - SO VERY SORRY - UPON DOT INSPECTION - REAR DOOR HANDLE IS LOOSE IDLE, SEE JOB NOTES

11/28/2024 856042 UNIVERSAL FORD LINCOLN (I)
05/09/2024 840686 UNIVERSAL FORD LINCOLN (I)

**1 BULB OUT** 

02/20/2024 462461 NORTH STAR FORD SALES-CALGARY (I)
TES VEH MUST BE BOOSTED AFTER VEH SITS FOR 2 DAYS. SUSPECTS POSSIBI

02/01/2024 831699 UNIVERSAL FORD LINCOLN (I)

ced

ANY NEEDED FABRICATION, MODIFICATIONS OR PAINTING?

PAINTED TO MATCH - YES
STARTED, REQUESTED AMOUNT \$3,828.41 INCLUDING PO (103697492)
ED TO PASS INSP. STS REPLACEMENT VEH IS BEING ORDERED. CALLED HELEN
R: JSG.FLEET@GOV.AB.CA

11/14/2023 561777 SHAGANAPPI MOTORS (I)

TIRES BEING STORED OR IS THE DRIVER KEEPING THEM?

:M

05/04/2023 813191 UNIVERSAL FORD LINCOLN (I)

01/12/2023 804832 UNIVERSAL FORD LINCOLN (I)

: manifold is leaking and has broken bolts - total part (745.16)

) - PREVENTIVE MAINT. - THIS PART/SERVICE IS NOT PERMITTED FOR THIS VEH

') - PREVENTIVE MAINT. - REVIEW DETAILED JOB NOTES

STARTED, REQUESTED AMOUNT \$1,803.63 INCLUDING PO (97997674)

R: JSG.FLEET@GOV.AB.CA

**IARGES** 

\X \$96.83 - IN THIS CASE 13% = \$234.47 - \$96.83 IS THE MAX CHARGE. THANKS

RESTARTED, REQUESTED AMOUNT \$1,900.46 INCLUDING PO (97997674) . DECLINED DJUSTED CODING RESTARTED, REQUESTED AMOUNT \$1,900.46 INCLUDING PO (97997674) 'PLIES.- APPROVED 1/12/2023

11/30/2022 442773 NORTH STAR FORD SALES-CALGARY (I)

AP TIRES TO WWINTER, CK THE CHARGING SYSTEM, AND A SEMI ANNUAL INSPI

LL EXHAUST LEAK AT RH MANIFOLD AND ONE CENTER STUD IS BROKEN OFF. E Y IS THIS 3 HOURS FOR?

RA TIME TO REMOVE BROKEN HARDWARE THAT MAY OCCUR

STARTED, REQUESTED AMOUNT \$4,346.15 INCLUDING PO (97403468)

'HORIZATION. PENDING CLIENT AUTHORIZATION PROCESS HAS BEEN CANCELI
COULD BE REJECTED WITHOUT CAUSING ISSUES OR BEING SAFETY RELATED.

DW ON AMPERAGE, FAILED THE CARBON PILE TEST, DOES NOT HOLD ADEQUATION.

NOT DUE FOR SERVICE AND HAS BEEN REJECTED. IT WILL BE DUE IN 6 MONT SHOP SUPPLIES TO ACTUAL REPAIRS PERFORMED TO BE FAIR

07/21/2022 788862 UNIVERSAL FORD LINCOLN (I)

01/25/2022 780462 UNIVERSAL FORD LINCOLN (I)

RI PORTAL. 37.50 IF NEEDED

PINTINE BELT.

COLUMN TO BE REBUILT. EXTENSION HOUSING SEAL LEAKING TRANMISISON F

STARTED, REQUESTED AMOUNT \$1,624.31 INCLUDING PO (92745940)

RESTARTED, REQUESTED AMOUNT \$1,649.31 INCLUDING PO (92745940) R: JSG.FLEET@GOV.AB.CA

LY RATED FOR 850, TESTS AT 520, REQUIRES BATTERY. WILL REPLACE WITH 85 MONTHS OF WARRANTY ON IT. MOVING THE UNIT MAY CREATE MORE DOWNTH RESTARTED, REQUESTED AMOUNT \$1,880.16 INCLUDING PO (92745940) THORIZATION. PENDING CLIENT AUTHORIZATION PROCESS HAS BEEN CANCELL AZDA DECLINEDSAVINGS \$ 230.85 BTX

01/17/2022 777919 UNIVERSAL FORD LINCOLN (I)
RES WITH RIMS. REAPLCVE WIPER BLADES. CHECK FOR HAVING TO BOOST TO

3ACK THE TIRES? ON RIMS.

RE TREAD READINGS, IS THE DRIVER TAKING BACK THE TIRES? ON RIMS.

AND WILL TAKE ALL SEASONS \$ 345.01 ... ON HOLD .. NEED MORE INFOR .. VS TIRES THREAD DEPT INFOR @ /32 ... INFOR PLEASE..

√S TIRES THREAD DEPT INFOR @ /32 ... INFOR PLEASE..

EAD DEPTHS @/ 32? ECTION

ASWER WE NEED SUMMER TIRES TREAD DEPTH FOR THE P/O APPROVAL ....

E 14/32NDS ALL 4

. 750CCA, TESTS AT 220. WILL REPLACE WITH A 750CCA MOTOCRAFT 5YR WAR NT. - WHAT IS THIS CHARGE FOR NO NOTES ????

NT. - DIAG FOR ROTATIONAL NOISE FROM THE ENGINE.

01/13/2022 77605 UNIVERSAL FORD LINCOLN (I)
IN'T REPAIR NEED TO REPLACE TIRE

O SA DAGG. LINE DISCONNECTED

FA REQUEST

07/07/2021 467505 SHAGANAPPI MOTORS (I)

05/05/2021 4944 SUPERIOR TRUCK EQUIPMENT INC (I)

02/02/2021 757247 UNIVERSAL FORD LINCOLN (I)
ING IS BROKEN, REQUIRES LEAF SPRINGS. PASSENGER SIDE UPPER AND LOW
ECOMMEND TIRES. // MAINTENANCE RECOMMENDATIONS FROM THE ARI POR
MMERCIAL T/A, REASON:WORN AXLE: 1 LF: 4/32 RF: 4/32 TIRE SIZE:245/75
1.2HR PER LABOR GUIDE

D COMPLAINT, CAUSE AND CORRECTION

## 1 GLASS MASTERS

TED LAMP IN THE FRONT NEEDING MORE TIME FOR RAD....SENT FOR AUTH FO

STARTED, REQUESTED AMOUNT \$6,431.67 INCLUDING PO (87520355)
HIS PO SENT FOR APPROVAL..

N TIRES @ \$ 212.94 BTXCB VENDOR AND HE DROP TIRE PRICE TO NA ACCOUN

AIN, MAY BE AN ISSUE WITH TEH MODULE. WILL REQUIRE DIAGNOSTIC IF WE V

RESTARTED, REQUESTED AMOUNT \$6,334.71 INCLUDING PO (87520355)

HORIZATION. PENDING CLIENT AUTHORIZATION PROCESS HAS BEEN CANCELI

1 reprogramming.

RESTARTED, REQUESTED AMOUNT \$7,100.39 INCLUDING PO (87520355)

EQUIPPED WITH BAND STYLE SENSOR, REQUIRES TPMS12 (VALVESTEM) STYLI

RESTARTED, REQUESTED AMOUNT \$7,579.99 INCLUDING PO (87520355)
OSED TPMS, HE WILL CB TO LET US KNOW IF TPMS LIGH WAS ON BEFORE GOIL

JP, REPLACED

RESTARTED, REQUESTED AMOUNT \$7,861.74 INCLUDING PO (87520355)
THE TPMS ISSUE WAS MIS DIAGNOSED & IF THE JUNCTION BOX NEEDED TO BE RAM TO EITHIER SENSOR NEW JUNCTION BOX WILL NOT PROGRAM TO BAND

10/23/2020 197308 STONEY TRAIL MAZDA (I)

ERY E BATTERY

03/26/2020 48154 QUEST EMERGENCY LIGHTING (I)
RS WERE COMPLETED BEFORE
PARATIVE . RE RE PANELS AND ACCESS FANS AND FOUND BOTH FANS MOUNT

04/02/2020 07600334 KAL TIRE NORTH HILL SHOP CTR. - MICHELIN (N)
'INTERS - FRONTS ARE AT 4/32NDS., LEFT REAR AT 5/32NDS, RIGHT REAT AT 6/3
AN ROTIIVA AT PLUS 100, REASON:WORN AXLE: 1 LF: 4/32 RF: 4/32 TIRE SI.
: MAINT. - THIS ITEM IS NOT DUE FOR SERVICE AND HAS BEEN REJECTED.

JLY TIRES ON STANDING OFFER ALLOWED, UPDATE WITH NA TIRES

IS CLIENT. ONLY TIRES LISTED ARE GOODYEAR, YOKOHAMA, TOYO, BRIDGEST AL ACCOUNT BILLING (FROM KT BILLING).....PO ISSUED FOR \$1,305.00 BT

03/20/2020 191906 STONEY TRAIL MAZDA (I)
PASS INSPECTION-CORRECTIONS TO HAVE DONE WHERE CAGE WAS INSTALLE

**PLING** 

BOVE ADJUSTMENT(S) HAVE BEEN MADE TO THIS PO.

oor time(s) accordingly.

06/11/2019 184107 STONEY TRAIL MAZDA (I) MOTOR NOT WORKING

oor time(s) accordingly.

11/01/2019 709930 UNIVERSAL FORD LINC SALES LTD (I)
. REQUIRES HIGHMOUNT STOP LIGHT REPAIR, FRONT SWAY BAR BUSHINGS, DF

IT: 35.61 MM MIN. THK.: 34 MM

RTS & LABOR ITEMIZED

ED PARTS & LABOR ITEMIZED

FOR ENGINE OIL LEAK NEEDED BEFORE REPAIRS ARE SENT TO THE CLIENT FO

EVENTIVE MAINT. - NEED PARTS & LABOR ITEMIZED

VENTIVE MAINT. - NEED PARTS & LABOR ITEMIZED

R HIGH MOUNT BRAKE LIGHT REPAIR NEEDED

HRS 149.00 PARTS 29.50 X 2
BULB 0.60
EVENTIVE MAINT. - MENU PRICE(SERVICE) 180.00
VENTIVE MAINT. - 1.0HR 149.00 PARTS 51.00

F BACK IN FOR LEAK DIAG 1 HR 149.00
ES.

STARTED, REQUESTED AMOUNT \$4,215.18 INCLUDING PO (77579247)

JING UPDATE FROM VDR - ADDITIONAL ISSUES - REAR MAIN SEAL, 2 KEY FOBS...

RED...NEGOTIATED SAVINGS CAPTURED OF \$1,017.31...VERIFIED SUBTOTAL OF RESTARTED, REQUESTED AMOUNT \$5,331.09 INCLUDING PO (77579247)

E FOR A/C AND KEY FOB.....ADVISED F/A OF NOTES......CALLED SUPERVISOR M D CB WITH UPDATE ON KEY FOBS AND A/C COMPLAINT INE MOUNT, 3.5HRS BROKEN STUDS, 1.0HRS EXTRACT STRIPPEDMANIFOLD NL 5HRS Y-PIPE TO TAIL PIPE CLAMP))) INSPECTFOR OIL LEAK AND FOUND THAT R GOT APPROVAL FOR AMOUNT \$2084.86 BFT FOR THE REAR MAIN SEAL REPL . - HELLO, PLEASE SPEAK TO AN ARI TECH AT TEL # 1 800 363 7676,.. YOU GOT VE MAINT. - HELLO, PLEASE SPEAK TO AN ARI TECH YOU GOT APPROVAL FOR

R PRIOR TO SENDING FOR APPROVAL (NO INDIVIDUAL PART LINES LISTED) NOOR IS REQUESTING EXTRA 10.2 HRS LABOR.

EPLACE BROKEN STUDS. INVOICE STILL DOES NOT MATCH TOTAL AMOUNT. V ENT FOR APPROVAL...

LVICE AND RESEALED...

..

RESTARTED, REQUESTED AMOUNT \$7,107.35 INCLUDING PO (77579247) BOR. FA MARCUS R. TO CALL BACK. STILL ON HOLD FOR NOW.

04/03/2019 383277 NORTH STAR FORD SALES-CALGARY (I)

TL 9/19

NORTH STAR FORD SALES-CALGARY (I) 3T -- NO AUTH -- ISSUED REF# -- SENT FOR APPROVAL

AKING, REPLACE -- NEG LABOR OVERLAP FROM 7.7 TO 5.0HRS SAVINGS OF \$41 ED -- CALIPERS SEIZING -- REPLACE PADS ROTORSE AND CALIPERS : AND HAVE BEEN DISCARDED, REPLACE

D 1.0HRS NEG TO .3HRS SAVINGS OF \$108.50

STARTED, REQUESTED AMOUNT \$5,757.75 INCLUDING PO (77390331)
RS - WILL GET SECOND OPINION. OKAY TO PAY DIAG AND DOT IF COMPLETED THORIZATION. PENDING CLIENT AUTHORIZATION PROCESS HAS BEEN CANCELI

11/30/2018 179227 STONEY TRAIL MAZDA (I)

oor time(s) accordingly.

09/27/2018 177020 STONEY TRAIL MAZDA (I)

06/22/2018 175067 STONEY TRAIL MAZDA (I)

1 AXLE: 2 LEFT: 5 MM RIGHT: 5 MM

MM MIN. THK.: 2 MM AXLE: 2 LEFT: 5 MM RIGHT: 5 MM MIN. THK.: 5

09/04/2018 41134 QUEST EMERGENCY LIGHTING (I)

08/31/2017 167367 STONEY TRAIL MAZDA (I)

05/05/2017 162075 STONEY TRAIL MAZDA (I)

RIGHT FRT DOOR LOCK CYL, SEIZED, REPLACED...

07/12/2016 157170 STONEY TRAIL MAZDA (I) ED PO FOR \$779.34BT

REPLACE.....NO MEASUREMENTS, EXECESSIVELY LOOSE

03/08/2016 153132 STONEY TRAIL MAZDA (I)

PLACE, REPLACE (WITH EXTENDED MIRROR FOR TOWING) ... HOUSING CRAC

07/20/2015 273421 COUNTRY HILLS FORD (I)

ЗΤ

02/26/2015 04903117 KAL TIRE NORTH HILL SHOP CTR. - MICHELIN (N) EAN MCNICOLE (JAIL VAN)NO MILEAGE - SUPPLY TO JAIL AND THEY WILL HAVE STALL ON SUPPLIED RIM

01/26/2015 267060 COUNTRY HILLS FORD (I)

AULTY, REPLACE..

DRIVER .. MOTORCRAFT .. 850CCA... WARRANTY = 2 YRS FREE REPLACEMENT

02/27/2015 294561 NORTH STAR FORD SALES-CALGARY (I)

D,,, REC REPLACE,,, REAR PADS DOWN TO 3MM,,, REC REPLACE,,, PARK BRAKE STARTED, REQUESTED AMOUNT \$5,395.87 INCLUDING PO (50162702)

R: JSG.FLEET@GOV.AB.CA ELEASED.

IUMBERS BECAUSE THEY DID NOT MATCH ... ASKED VDR IF TRANSMISSION OUT

06/05/2014 139438 STONEY TRAIL MAZDA (I)
ALL BACK TO FINALIZE

04/22/2014 3000803 GLASS MASTERS (I) UED PO# AND PAID \$207.45 AT HECKS OK

02/19/2014 252546 CAM CLARK FORD (I)
CERTIFICATE WAS RECORDED. PAID \$ 361.68 B/T TO S/A.

08/15/2013 HISTORY PO ACCOUNT (I) 07/12/2013 HISTORY PO ACCOUNT (I) HISTORY PO ACCOUNT (I) 12/07/2012 11/13/2012 HISTORY PO ACCOUNT (I) HISTORY PO ACCOUNT (I) 04/19/2012 02/10/2012 HISTORY PO ACCOUNT (I) 10/07/2011 HISTORY PO ACCOUNT (I) 06/17/2011 HISTORY PO ACCOUNT (I) 05/11/2011 HISTORY PO ACCOUNT (I) HISTORY PO ACCOUNT (I) 03/02/2011 02/08/2011 HISTORY PO ACCOUNT (I) 09/24/2010 HISTORY PO ACCOUNT (I)