

12/02/2022 04:26 P.M. : AUTO_RESPONSE: AUTHORIZED BY CLIENT - \$1,775.39

12/02/2022 04:26 P.M. : AUTO_RESPONSE: VENDOR EMAILED

12/05/2022 08:08 P.M. : TaxExempt

05/19/2022 1:01 PM	05/19/2022	141565	0	\$442.73	PAID	05/19/2022	262006
--------------------	------------	--------	---	----------	------	------------	--------

05/19/2022 01:02 P.M. : CHANGE ENGINE OIL AND FILTERREPLACE REAR DIFFERNTIAL FLUID BASED ON TIME AND M

05/19/2022 01:04 P.M. : PO APPROVED FOR \$442.73 BY HOLMAN ON 05/19/2022

05/19/2022 01:29 P.M. : TaxExempt

12/03/2021 11:00 AM	12/03/2021	141229	0	\$1,032.56	PAID	12/09/2021	16099
---------------------	------------	--------	---	------------	------	------------	-------

12/03/2021 11:31 A.M. : GROWLING NOISE WHILE DRIVING, RF WHEEL BEARING AND HUB BEARING HAVE FLAT SPO

12/03/2021 11:35 A.M. : PM MAINT AND WINTERIZE BLOCK HEATER FAILED

12/03/2021 11:38 A.M. : LP BULB OUT

12/03/2021 11:39 A.M. : BLOCK HEATER FAILED HEATING ELEMENT OPEN

12/03/2021 11:45 A.M. : PO APPROVED FOR \$837.74 BY ARI ON 12/03/2021

12/03/2021 11:45 A.M. : WO# 16099

12/06/2021 04:44 P.M. : SHOP CLLD TO ADD TO PO

12/06/2021 04:44 P.M. : SHOP STS TENSIONER AND PULLEY MAKING NOISE

12/09/2021 11:50 A.M. : TaxExempt

06/10/2020 11:04 AM	06/10/2020	136441	0	\$134.22	PAID	06/10/2020	242497
---------------------	------------	--------	---	----------	------	------------	--------

06/10/2020 11:05 A.M. : CHANGE ENGINE OIL AND FILTER, FILL LOW WASHER FLUID, REPLACE PLUGGED AIR FILTE

06/10/2020 11:06 A.M. : PO APPROVED FOR \$134.22 BY ARI ON 06/10/2020

06/10/2020 11:07 A.M. : TaxExempt

06/08/2020 4:00 PM	06/08/2020	136338		\$375.63	PAID	07/02/2020	8752-440111
--------------------	------------	--------	--	----------	------	------------	-------------

06/08/2020 04:32 P.M. : WINDSHIELD IS CRACKED

06/08/2020 04:34 P.M. : WO #875244011

06/08/2020 04:34 P.M. : PO APPROVED FOR \$375.63 BY ARI ON 06/08/2020

06/29/2020 12:59 P.M. : 8752-440111

06/29/2020 12:59 P.M. : BG20171 -- INVOICE 8752-440111 CAME IN AT 375.63

04/29/2019 11:16 AM

04/12/2019 1:16 PM	04/12/2019	132240		\$1,568.33	PAID	08/16/2019	0811060798
--------------------	------------	--------	--	------------	------	------------	------------

04/12/2019 01:17 P.M. : GOF, CHECK AND TEST BATTERY , GOOD SEASONAL CHECK OVER

04/12/2019 01:22 P.M. : CHARGE AND TEST BATTERY , BATTERY WAS RIGHT DEAD .. STILL CHARGING

04/12/2019 01:29 P.M. : seasonal inspection for season start up

04/12/2019 01:29 P.M. : PO APPROVED FOR \$183.60 BY ARI ON 04/12/2019

04/15/2019 11:34 A.M. : BATTERY FAILED TEST . NEEDS BATTERY REPLACED

04/15/2019 11:42 A.M. : UPON VEHICLE INSPECTION FOUND NEEDS ALL 4 BALL JOINTS ,

04/15/2019 11:47 A.M. : NEEDS LEFT OUTER TIE ROD AND ALIGNMENT

04/15/2019 12:07 P.M. : 32001001 - BATTERY - PARTS - PLEASE ADVISE NEW BATTERY BRAND AND WARRANTY AS I

04/15/2019 12:08 P.M. : 16001015 - LOWER BALL JOINT - PARTS - WHY DOES IT NEED BALL JOINTS WHAT ARE THEI

04/15/2019 12:09 P.M. : 15004024 - TIE ROD, LH OUTER - PARTS - WHY DOES IT NEED THE TIE ROD? IS IT LOOSE, E

04/15/2019 12:09 P.M. : APC WEB REVIEW ... MORE INFO NEEDED

04/15/2019 12:09 P.M. : WAITING FOR VENDOR NOTES

04/15/2019 12:23 P.M. : 15004024 - TIE ROD, LH OUTER - PARTS - PART IS VERY LOOSE

04/15/2019 12:23 P.M. : 16001015 - LOWER BALL JOINT - PARTS - BALL JOINTS ARE ALL VERY LOOSE

04/15/2019 12:23 P.M. : 32001001 - BATTERY - PARTS - TESTED AT 8.8. AND DID NOT CHANGE WHEN TEMPERATUR

04/15/2019 12:39 P.M. : 32001001 - BATTERY - PARTS - STILL NEED YOU TO DOCUMENT THE BRAND OF THE NEW B

04/15/2019 12:39 P.M. : WAITING FOR VENDOR NOTES

04/15/2019 01:00 P.M. : 32001001 - BATTERY - PARTS - CANADIAN ENERGY . 850 CCA AND 18 MNTH WARRANTY

04/15/2019 01:05 P.M. : APC WEB REVIEW ... SENT FOR AUTH

04/15/2019 01:05 P.M. : AUTO_RESPONSE: CLIENT AUTHORIZATION PROCESS HAS BEEN STARTED, REQUESTED AI

04/25/2019 04:43 P.M. : AUTO_RESPONSE: CLIENT AUTHORIZATION PROCESS HAS BEEN RESTARTED, REQUESTED

04/29/2019 11:10 A.M. : AUTO_RESPONSE: AUTHORIZED BY CLIENT - \$1,723.18

04/29/2019 11:19 A.M. : VENDOR RECIEVED APPROVAL ON PARTNER CONNECT

05/03/2019 04:30 P.M. : This PO is tax exempted due to undefined and request submitted by NICKI

08/29/2018 9:32 PM	08/29/2018	131458		\$1,214.00	PAID	08/29/2018	RO33433
--------------------	------------	--------	--	------------	------	------------	---------

08/29/2018 09:33 P.M. : request for install four new tires
08/29/2018 09:33 P.M. : request approval for four new tires as all four tires are worn out
08/29/2018 09:36 P.M. : all four tires on this unit are worn out - we are therefore requesting approval for four new tires
08/29/2018 09:39 P.M. : TIRE SIZE:265/70 R17, MANUFACTURER:GENERAL, MODEL:ATX, REASON:WORN AXLE: 1 LF:
08/29/2018 09:40 P.M. : PO APPROVED FOR \$1,214.00 BY ARI ON 08/29/2018
08/29/2018 09:41 P.M. : TaxExempt
08/29/2018 7:38 PM 08/29/2018 131458 \$106.25 PAID 08/29/2018 RO33288
08/29/2018 07:38 P.M. : OIL CHANGE AND SERVICE
08/29/2018 07:40 P.M. : PO APPROVED FOR \$106.25 BY ARI ON 08/29/2018
08/29/2018 07:40 P.M. : TaxExempt
07/27/2018 11:22 AM 07/27/2018 128322 \$75.05 PAID 07/27/2018 RO32513
07/27/2018 11:23 A.M. : OIL CHANGE
07/27/2018 11:28 A.M. : APC REVIEWED
07/27/2018 11:28 A.M. : PO APPROVED FOR \$75.05 BY ARI ON 07/27/2018
07/27/2018 11:28 A.M. : VENDOR EMAIL SENT. TO: SUBJECT: REPAIR AUTHORIZATION
07/27/2018 11:41 A.M. : TaxExempt
07/04/2018 6:56 PM 07/04/2018 125694 \$63.90 PAID 07/05/2018 RO31892
07/04/2018 06:56 P.M. : flat tires
07/05/2018 11:10 A.M. : 17008011 - TPMS RESEAL KIT - LABOR - WHICH TIRE ARE YOU REPAIRING?
07/05/2018 11:10 A.M. : 17008011 - TPMS RESEAL KIT - PARTS - WHICH TIRE ARE YOU REPAIRING?
07/05/2018 11:10 A.M. : WAITING FOR PARTS
07/05/2018 12:10 P.M. : LR FLAT & SPARE VALVE STEM & KIT
07/05/2018 12:11 P.M. : PO APPROVED FOR \$63.90 BY ARI ON 07/05/2018
07/05/2018 12:11 P.M. : AUTH \$ 63.90 TO CAROL
07/05/2018 12:13 P.M. : TaxExempt
06/09/2018 1:16 PM 06/09/2018 123811 \$112.60 PAID 06/09/2018 31378
06/09/2018 01:18 P.M. : OIL CHANGE
06/09/2018 01:20 P.M. : PO APPROVED FOR \$112.60 BY ARI ON 06/09/2018
06/09/2018 01:20 P.M. : VENDOR EMAIL SENT. SUBJECT: REPAIR AUTHORIZATION
06/09/2018 01:35 P.M. : TaxExempt
10/10/2017 12:00 AM 10/10/2017 118034 \$74.20 PAID 10/18/2017 0811050713
08/31/2017 12:00 AM 08/31/2017 113034 \$35.95 PAID 09/08/2017 0811049929
08/24/2017 12:00 AM 08/24/2017 111242 \$74.20 PAID 08/31/2017 0811049826
07/27/2017 12:00 AM 07/27/2017 108213 \$35.95 PAID 08/04/2017 0811049258
06/17/2017 12:00 AM 06/17/2017 105838 \$73.70 PAID 06/19/2017 0811048467
06/07/2017 12:00 AM 06/07/2017 107100 \$19.40 PAID 08/01/2017 0811048857
07/07/2016 12:00 AM 07/07/2016 99822 \$68.59 PAID 07/09/2016 205864
07/09/2016 10:35 A.M. : MAINTENANCE
05/26/2016 12:00 AM 05/26/2016 94586 \$125.02 PAID 05/26/2016 204835
05/26/2016 06:06 P.M. : GENERAL MAINTENANCE
02/19/2016 12:00 AM 02/19/2016 93705 \$71.29 PAID 02/19/2016 202588
02/19/2016 01:31 P.M. : GENERAL MAINTENANCE
06/25/2015 5:00 PM 06/25/2015 85778 \$315.25 PAID 06/25/2015 196223
06/25/2015 05:04 P.M. : WO#198902 ... ISSUED PO
06/25/2015 05:04 P.M. : IN FOR LOF, AIR FILTER DIRTY, WIPERS TORN, BELT WORN, REPLACE
06/25/2015 05:06 P.M. : PO APPROVED FOR \$309.76 BY ARI ON 06/25/2015
06/25/2015 05:07 P.M. : PO APPROVED FOR \$315.25 BY ARI ON 06/25/2015
06/25/2015 05:26 P.M. : PAID BRIAN \$ 315.25
04/24/2015 3:00 PM 04/24/2015 77573 \$1,479.49 PAID 04/24/2015 6011
04/24/2015 03:43 P.M. : WO#6011...ATF...PAID \$1479.49 AT....
04/24/2015 03:43 P.M. : LOF...SAFETY INSPECTION...
04/24/2015 03:44 P.M. : D/C OF VIBRATION - DIAG AND FOUND REAR DRIVE SHAFT BENT-REPLACE...
04/24/2015 03:46 P.M. : FRONT PADS WORN TO 1MM - FRONT ROTORS ARE UNDERSIZED - VDR DID NOT RECORD S
04/24/2015 03:48 P.M. : PO APPROVED FOR \$1,479.49 BY ARI ON 04/24/2015
04/15/2015 12:00 AM 04/15/2015 77500 \$1,089.65 PAID 06/12/2015 1216316

06/08/2015 03:15 P.M. : WO 37960--ATF CLAIM, PM OK

06/08/2015 03:16 P.M. : SUPPLIED TIRES TO CLIENT DIRECTLY, TOYO OPEN COUNTRY CT, LT245-75-17, PC 345030

06/08/2015 03:16 P.M. : PO APPROVED FOR \$1,153.60 BY ARI ON 06/08/2015

06/12/2015 09:53 A.M. : SERVICE DATE...04/15/15

07/04/2014 2:00 PM	07/04/2014	72380	\$295.01	PAID	07/04/2014	4819
--------------------	------------	-------	----------	------	------------	------

07/04/2014 02:44 P.M. : WO 4819 ATF

07/04/2014 02:45 P.M. : ABS LIGHT ON. ABS ACTIVATING ON ITS OWN => SCANNED. L/R SENSOR NO SIGNAL. BR

07/04/2014 02:46 P.M. : LOF

07/04/2014 02:47 P.M. : PO APPROVED FOR \$295.01 BY ARI ON 07/04/2014

05/06/2014 12:00 AM	05/06/2014	64917	\$184.00	PAID	05/15/2014	04544406
04/23/2014 12:00 AM	04/23/2014	65336	\$247.50	PAID	05/29/2014	4459
08/14/2013 12:00 AM	08/14/2013	62991	\$64.15	PAID	08/14/2013	
06/05/2013 12:00 AM	06/05/2013	57690	\$61.48	PAID	06/05/2013	
04/15/2013 12:00 AM	04/15/2013	55325	\$992.37	PAID	04/15/2013	
07/06/2012 12:00 AM	07/06/2012	52734	\$244.63	PAID	07/06/2012	
04/09/2012 12:00 AM	04/09/2012	49245	\$768.16	PAID	04/09/2012	
10/07/2011 12:00 AM	10/07/2011	47834	\$61.48	PAID	10/07/2011	
07/28/2011 12:00 AM	07/28/2011	42726	\$119.26	PAID	07/28/2011	
07/14/2011 12:00 AM	07/14/2011	42726	\$57.01	PAID	07/14/2011	
09/02/2010 12:00 AM	09/02/2010	35519	\$51.48	PAID	09/02/2010	
06/07/2010 12:00 AM	06/07/2010	29676	\$50.48	PAID	06/07/2010	
04/19/2010 12:00 AM	04/19/2010	26604	\$480.24	PAID	04/19/2010	
08/18/2009 12:00 AM	08/18/2009	24000	\$50.48	PAID	08/18/2009	
06/17/2009 12:00 AM	06/17/2009	19000	\$90.47	PAID	06/17/2009	
04/30/2009 12:00 AM	04/30/2009	14000	\$50.48	PAID	04/30/2009	
03/05/2009 12:00 AM	03/05/2009	13712	\$152.00	PAID	03/05/2009	
02/10/2009 12:00 AM	02/10/2009	13712	\$58.03	PAID	02/10/2009	

Vendor

GARY MOE CHRYSLER JEEP DODGE (N)

AT THE BRAKES ?... THE LAST FRONT SE
?... PLEASE DOCUMENT THE TIRE TREAT

EEN INSPECTED, WE CAN DO A FRONT WH
EFT REAR HAS 15/3NDS AND THE RIGHT RE
MOUNT \$2,263.01 INCLUDING PO (10815009

) AMOUNT \$4,865.12 INCLUDING PO (108150

CHAD'S AUTO SERVICE LTD (I)
: PADS AT 1 MM, ROTORS GROOVED BEYON

KIRK'S MIDWAY TIRE (N)

MOUNT \$1,889.28 INCLUDING PO (10570824

MOBIL 1 LUBE EXPRESS (I)

MOBIL 1 LUBE EXPRESS (I)
AIR FILTER

CHAD'S AUTO SERVICE LTD (I)

DIATOR HOSE CLAMPS , RETORQUE CLAMP

ORN , R& I TWO PLUGS TO INSPECT BOOTS

MOUNT \$1,775.39 INCLUDING PO (97486821

MOBIL 1 LUBE EXPRESS (I)
MILEAGE AND ARI RECOMMENDATIONSREP

CHAD'S AUTO SERVICE LTD (I)
ITS

MOBIL 1 LUBE EXPRESS (I)
:R, REPLACE INOPERATIVE LEFT BRAKE LICK

SPEEDY AUTO GLASS - BELRON (N)

FOUNTAIN TIRE - #081 - CORP (I)

WELL AS THE TEST RESULTS ON THE OLD
R CONDITION? ARE THEY LOOSE, BROKEN,
BROKEN, WORN?

E ADJUSTED
ATTERY,, CCA'S, AND WARRANTY PLEASE.

MOUNT \$1,723.18 INCLUDING PO (77574649
) AMOUNT \$1,723.18 INCLUDING PO (775746

OK TIRE AUTO SERVICE (I)

232/32 RF: 232/32 TIRE SIZE:265/70 R1

OK TIRE AUTO SERVICE (I)

OK TIRE AUTO SERVICE (I)

OK TIRE AUTO SERVICE (I)

OK TIRE AUTO SERVICE (I)

FOUNTAIN TIRE - #081 - CORP (I)

FOUNTAIN TIRE - #081 - CORP (I)

FOUNTAIN TIRE - #081 - CORP (I)

FOUNTAIN TIRE - #081 - CORP (I)

FOUNTAIN TIRE - #081 - CORP (I)

FOUNTAIN TIRE - #081 - CORP (I)

MOBIL 1 LUBE EXPRESS (I)

MOBIL 1 LUBE EXPRESS (I)

MOBIL 1 LUBE EXPRESS (I)

MOBIL 1 LUBE EXPRESS (I)

CHAD'S AUTO SERVICE LTD (I)

3PECSREAR PADS AT 1MM ...ROTORS AT

O.K. TIRE - TOYO TIRE (N)

CHAD'S AUTO SERVICE LTD (I)

LOKEN HARNESS.

MICHELIN NORTH AMERICA CANADA (N)

CHAD'S AUTO SERVICE LTD (I)

HISTORY PO ACCOUNT (I)

HISTORY PO ACCOUNT (I)

HISTORY PO ACCOUNT (I)

HISTORY PO ACCOUNT (I)

HISTORY PO ACCOUNT (I)

HISTORY PO ACCOUNT (I)

HISTORY PO ACCOUNT (I)

HISTORY PO ACCOUNT (I)

HISTORY PO ACCOUNT (I)

HISTORY PO ACCOUNT (I)

HISTORY PO ACCOUNT (I)

HISTORY PO ACCOUNT (I)

HISTORY PO ACCOUNT (I)

HISTORY PO ACCOUNT (I)

HISTORY PO ACCOUNT (I)

HISTORY PO ACCOUNT (I)